

DIY & Synth Meetup 2023 Panel Build Guide

Place LEDs like seen on the picture. Long leg is plus.

Place resistors like seen here. Resistors are equal and they have no polarity.

Place the SMD pin header, solder one corner first, then you still have the chance to correct it. When it sits correctly, solder all other legs.

White stripe = red stripe of your bus cable.

Done!

Hope you enjoy it. If you need more DIY stuff, feel free to visit our shop.



www.exploding-shed.com